

**2006 JLG E300AJ  
 30' ARTICULATING BOOM**

|  |                    |                                     |      |                                     |             |                                     |      |                          |
|--|--------------------|-------------------------------------|------|-------------------------------------|-------------|-------------------------------------|------|--------------------------|
| Rental#                                      | J06135             |                                     |      |                                     |             |                                     |      |                          |
| Hours:                                       | 980.3              |                                     |      |                                     |             |                                     |      |                          |
| Serial Number:                               | 300099200          |                                     |      |                                     |             |                                     |      |                          |
| Engine Manufacturer:                         | N/A                |                                     |      |                                     |             |                                     |      |                          |
| Engine Overall Condition:                    | Poor               | <input type="checkbox"/>            | Fair | <input type="checkbox"/>            | Good        | <input type="checkbox"/>            | Exc. | <input type="checkbox"/> |
| Fuel:  | Electric           |                                     |      |                                     |             |                                     |      |                          |
| Drive Type:                                  | 2WD                |                                     |      |                                     |             |                                     |      |                          |
| Steering:                                    | 2-Wheel            |                                     |      |                                     |             |                                     |      |                          |
| Tire Fill:                                   | Solid              |                                     |      |                                     |             |                                     |      |                          |
| Remaining Tire %:                            | FL                 | <u>20</u>                           | FR   | <u>20</u>                           | RL          | <u>20</u>                           | RR   | <u>20</u>                |
| Mismatched Tires?                            | Yes                | <input type="checkbox"/>            | No   | <input checked="" type="checkbox"/> |             |                                     |      |                          |
| Paint Condition?                             | Poor               | <input checked="" type="checkbox"/> | Fair | <input type="checkbox"/>            | Good        | <input type="checkbox"/>            | Exc. | <input type="checkbox"/> |
| Sheet Metal Condition?                       | Poor               | <input type="checkbox"/>            | Fair | <input type="checkbox"/>            | Good        | <input checked="" type="checkbox"/> | Exc. | <input type="checkbox"/> |
| Basket Size?                                 | 4'                 | Damage?                             | Yes  | <input checked="" type="checkbox"/> | No          | <input type="checkbox"/>            |      |                          |
| Cylinder Leaks?                              | Yes                | <input type="checkbox"/>            | No   | <input checked="" type="checkbox"/> |             |                                     |      |                          |
| Cylinder Damage?                             | Yes                | <input type="checkbox"/>            | No   | <input checked="" type="checkbox"/> |             |                                     |      |                          |
| Boom Damage?                                 | Yes                | <input type="checkbox"/>            | No   | <input checked="" type="checkbox"/> |             |                                     |      |                          |
| Wheel Seals Leak?                            | Yes                | <input type="checkbox"/>            | No   | <input checked="" type="checkbox"/> |             |                                     |      |                          |
| Controls & Safety Switches Operate Properly? | Yes                | <input checked="" type="checkbox"/> | No   | <input type="checkbox"/>            |             |                                     |      |                          |
| All Safety Decals Legible?                   | Yes                | <input checked="" type="checkbox"/> | No   | <input type="checkbox"/>            |             |                                     |      |                          |
| Other Damage?                                |                    |                                     |      |                                     |             |                                     |      |                          |
| Rent Ready?                                  | Yes                | <input checked="" type="checkbox"/> | No   | <input type="checkbox"/>            |             |                                     |      |                          |
| Options:                                     |                    |                                     |      |                                     |             |                                     |      |                          |
| Skypower Installed & Working                 | Yes                | <input type="checkbox"/>            | No   | <input checked="" type="checkbox"/> | Welder size |                                     |      |                          |
| Date Last Annual Inspection:                 | March 2017         |                                     |      |                                     |             |                                     |      |                          |
| Notes:                                       |                    |                                     |      |                                     |             |                                     |      |                          |
| Inspected by:                                | Paul               |                                     |      |                                     |             |                                     |      |                          |
| Price  | <b>\$11,100.00</b> |                                     |      |                                     |             |                                     |      |                          |



[CLICK FOR EQUIPMENT SPECIFICATIONS](#)

**FINANCING AVAILABLE**

**Decatur, IL 62521**  
 4041 N. Brush College Rd.  
 Phone# 217-872-0980

**Granite City, IL 62040**  
 10 Central Industrial Dr.-Bldg 8  
 Phone# 618-451-2139

**Morton, IL 61550**  
 945 Detroit Ave  
 Phone# 309-266-8700

**Indianapolis, IN 46077**  
 5520 West 96th St.  
 Phone# 317-733-8010

**Lafayette, IN 47909**  
 2835 Concord Road  
 Phone# 765-477-1155

**Terre Haute, IN 47805**  
 1151 E Park Ave.  
 Phone# 812-234-1111

**Louisville, KY 40299**  
 10700 Bluegrass Parkway  
 Phone# 502-493-3780

**Clarksville, TN 37040**  
 2281 Wilma Rudolph Blvd.  
 Phone# 931-802-6730

**Knoxville, TN 37920**  
 914 A Maryville Pike  
 Phone# 865-219-1737